



It's shipping & survey

CISS GROUP PTE.LTD.

Registry address: 10 Anson Road , # 20-05,
International Plaza, Singapore, 079903
Reg.No 201618838R
Operation office: 77 Science Park Drive Str.,
CINTECH III Business Center, #03-25/26,
Singapore 118256

DAILY SURVEY REPORT

Vessel/ Installatio : XXXX Location : Batu Ampar, Indonesia
 Customer : XXXX Date : XX.XX.2023
 Job number : SGD00XXX Client Ref No : XXXX

RECORD OF STEEL DURING LOADING - CARGO SURVEY

HOLDS LOADED #1, 2, 3, 4

INSPECTION PROVIDED: General view and surface condition of the pipes, steel rope, pipes surface condition

Time sheet



Date	Time		Operations	Holds
	from	to		
XX.XX.2023	8:00 LT	9:30 LT	no loading operations due to rain	X
	9:40 LT	12:00 LT	Loading operations and lashing	1, 2, 3, 4
	12:00 LT	13:30 LT	lunch break	X
	13:30 LT	14:30 LT	no loading operations due to rain	X
	14:30 LT	17:00 LT	Loading operations and lashing	1, 2, 3, 4
	17:00 LT	19:30 LT	lunch break	X

Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023




PHOTO REPORT

Day Shift

Hold № 4



Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



Water in the Hold №4



Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023
Hold №3




Hold № 2




Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



Hold No 1



Steel rope



Pipes surface condition

Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



Daily Survey Report / XXXX / Batu Ampar, Indonesia / XX.XX.2023



THE END OF REPORT

Dated: XX of XXXX, 2023

